WorldWEIGH C100 Counting Scale Top End Counting

- Place pieces to be counted on scale minus a small sample size

- Tare scale

- Add sample size to scale, then key in sample size and press the sample key

- Tare scale again

- Remove pieces, display will show a negative number telling how many pieces have been removed